



Inspection Report

Report Date 1/13/2016

Company A 'N' B Home Inspections
Address 21362 S. 213th Pl.
Queen Creek, AZ. 85142

Customer Mr. and Mrs. John Doe
Site Address 1234 Main St.
Anytown, AZ. 85XXX

Thermographer Erik Diener

Contact Person




Image and Object Parameters

Text Comments

Camera Model	Z-Camera
Image Date	1/13/2016 11:30:43 AM
Image Name	IR_0647.jpg
Emissivity	0.95
Reflected apparent temperature	68.0 °F
Object Distance	3.3 ft

Description

1234 Main St. Anytown, AZ. 85XXX
Hall Bathroom Ceiling.



Inspection Report

Report Date 1/13/2016

Company A 'N' B Home Inspections
Address 21362 S. 213th Pl.
Queen Creek, AZ. 85142

Customer Mr. and Mrs. John Doe
Site Address 1234 Main St.
Anytown, AZ. 85XXX

Thermographer Erik Diener

Contact Person




Image and Object Parameters

Text Comments

Camera Model	Z-Camera
Image Date	1/13/2016 11:31:23 AM
Image Name	IR_0650.jpg
Emissivity	0.95
Reflected apparent temperature	68.0 °F
Object Distance	3.3 ft

Description

1234 Main St. Anytown, AZ. 85XXX
Master Bathroom Ceiling



Inspection Report

Report Date 1/13/2016

Company A 'N' B Home Inspections
Address 21362 S. 213th Pl.
Queen Creek, AZ. 85142

Customer Mr. and Mrs. John Doe
Site Address 1234 Main St.
Anytown, AZ. 85XXX

Thermographer Erik Diener

Contact Person




Image and Object Parameters

Text Comments

Camera Model	Z-Camera
Image Date	1/13/2016 11:31:51 AM
Image Name	IR_0652.jpg
Emissivity	0.95
Reflected apparent temperature	68.0 °F
Object Distance	3.3 ft

Description

1234 Main St Anytown, AZ. 85XXX
Master Bedroom Ceiling



Inspection Report

Report Date 1/13/2016

Company A 'N' B Home Inspections
Address 21362 S. 213th Pl.
Queen Creek, AZ. 85142

Customer Mr. and Mrs. John Doe
Site Address 1234 Main St.
Anytown, AZ. 85XXX

Thermographer Erik Diener

Contact Person




Image and Object Parameters

Text Comments

Camera Model	Z-Camera
Image Date	1/13/2016 11:32:22 AM
Image Name	IR_0654.jpg
Emissivity	0.95
Reflected apparent temperature	68.0 °F
Object Distance	3.3 ft

Description

1234 Main St. Anytown, AZ. 85XXX
Master Bedroom Ceiling